Reproduced from the holdings of the National Archives Holmes & NARVER, Inc.

THE NEW TLD

TO (CHK'D.

ant

N 406133 A TO. C. L. East c FROM: David L. Narver, Jr. RE. Discrepancies Between Drawings and Instrumentation Chart E DATE: November 19, 1953 F G Reference your meme dated November 18, 1953. ĸ Station No. М Utilizes portion of existing IVY Station 300 -1811.03 No H&N work. 0 See drawing 3328-KE-6, Note 7. ARCHIVES 711 a REPOSITORY PACIFIC SOUTHWEST REGION Deleted 1403.17 S COLLECTION RG 326 ATOMIC ENERGY COMMISSION 232+09 Deleted Deleted 232.10 BOX No. 199624 (#608) A16334 326-65 VO170 Deleted 232.11 V Deleted 232.12 SURVEYS w FOLDER AUGUST 1, 1953 ON

A user furnished rack in Station 60 -61 Y No H&N work. z BEST COPY AVAILABLE Same as 2231.01 2231 Station runs from Ruby to Sally so either location 2230 satisfactory Is on Sally; however, because it is a detail of the 2231.01 2230 drawings, the title on the drawing refers to the primary Station (2230) location. Deleted 232.08 Pipe between Sugar & Tare - Either location should 2220 TERMINATION (CIRCLE NUMBER(S))
CLASSIFICATION RETAINED
CLASSIFICATION RETAINED
CLASSIFICATION RETAINED
CONTRINS NO CHANGED TO:
CONTRINS NO CHANGED
LIASSIFICATION CANCELLED
LIASSIFICATION CANCELLED suffice. a**£221.02** Actually on Tare but same condition as 2231.01. · A user furnished rack in Station 50 - No H&N work. Tare - Drawing 6293 being revised. Tare - Drawing 6293 being revised. All information required in on drawing 3384-H0-3, 58555562.02 Note 3. All information required in on drawing 2203-0B-1. B12.01 thru **9931.2.05** "This material contains information affecting the

the assessment of the rights states within the meangreen, the state of the control of the by faw.

he holdings of the National Archives HOLMES & NARVER, Inc.

TO CHK'D.

TO: C. L. East	JOB: <u>88l</u>	A B			1
FROM. David L. Nar	ver, Jr. RE: Discrepancies Between Drawings and Instrumentation Chart Page Two DATE: November 19, 1953	C D E F		·	
Station No.		G			
1354 1355 1356	Theoretically on reef between Delta & Able - So either site is correct. Ditto Ditte	K L M N			
232.03	Deleted	PQ			1
1811.01	Part of Station 1341.	R S			-
1402 1403.15 1403.16	On drawing 6337-AB-3 - to be field located. Deleted Deleted	v w x			1
10)) 30)) 40)) 90))	We assigned the name of the nearest island so as to indicate which part of lagoon.	Z]
11 31 41 91	User furnished rack in Station 10 - No H&N work. User furnished rack in Station 30 - No H&N work. User furnished rack in Station 40 - No H&N work. User furnished rack in Station 90 - No H&N work.	1			
143.01 thru 143.44	User requested anchors shown on drawing be stored at Tare until needed. Actual lagoon location not known.				
144.01 thru 144.16	Ditto above.	•			
1111)) 1112)) 1113)) 1114))	Drawing 6402-F0-3 shows details. Drawing being r to indicate locations.	evise	d		
1216	At Station 30. Net possible to distinguish betwe 1216 and 30.	en			
162.01	Location shown on drawing 2209-NA-1 and 3387-NA-6 All required details are as shown on 3387-NA-6.	•			
710	Ditto 162.01.				

Reproduction the holdings of the National Archives BOLMES & NARVER, Inc.

ENGINEERS

TO: C. L. East 884 Discrepancies between drawings and FROM: David L. Narver, Jr. RE: Instrumentation Chart

Page Three

DATE: November 19, 1953

Station Number

120.12

Location as per Civil drawings 2202 and 2229.

1350.01 thru

Theoretically on reef very close to Station 20-Charlie.

1350.12

1110

Drawing 6403-CH-3 shows details. Now that number is known, the drawing is being

revised to show number.

TO |CHK'D. н N A B C D E F G 1 J ĸ L М 0 Q R T U v W Y

BLNJr: eas

David L. Narver, Jr. Chief Project Engineer

cci Manager, Constr. - Oper. Div. Chief of Constr. - Oper. Div. Project Engineering File Central File